

VEC Hybrid Pendulum Pendant
Instructor: Scott Mason & Phyllis Flora

Required Tools:

*tools available to share at the Ed Center but feel free to bring your own

Bench block
Rawhide hammer or nylon mallet
Sanding sticks or metal files
Round nose pliers
Sandpaper
Metal shears
Jeweler's saw and sawblades (3/0 or 4/0)
Cut Lube or beeswax
Bench pin
Stone setting tools
Digital caliper
Mitre jig (optional)
Flush cutters
Steel ring mandrel
Jewelry-making pliers (flat nose, chain nose, round nose)
Soldering set-up:
 Torch (butane micro torch)
 Flux
 Pickle
 Fireproof surface (e.g., Solderite board or charcoal block)
 Solder pick
 Cross-lock tweezers
 Hard, medium and easy solder
 Quench bowl